


J/24 MAST SET UP FOR MEASUREMENT

SETTING THE MAST UP FOR MEASUREMENT

1. Place the lower edge of a 20 mm band 7725 mm down from the top forestay fixing point.
(Rules 3.5.2 & 3.5.3 b)
2. Place a band on the mast so that the upper edge is parallel with the lower edge of boom bolt rope track when the boom is held at right angles to the mast. (Rule 3.5.2.d)
3. Place a band at the top of the mast so that the lower edge is not more than 8538 mm above the upper edge of the band placed in 2. (Rule 3.5.2 d)
4. Place a band at the outer end of the boom so that the edge closest to the mast is no more that 2970 mm from the aft surface of the mast when the boom is held at right angles to the mast. (Rule 3.5.5 c)



Lorne Chapman
August 4 1997
Ver 1.2